


CUSTOMER	
REPORT TYPE	Incoming Inspection Report
DATE	29.03.2023
AIRCRAFT MANUFACTURER	Bombardier
AIRCRAFT MODEL	CL 850
AIRCRAFT S/N	
REGISTRATION	
VENUE	
CREATED AT	25.08.2023
CREATED BY	

Incoming Inspection Report



#1

#1 POCKET DOOR LOWER PANEL

Category: Interior

Created By:

Sub-Category:

Created At: 31.01.2023, 11:57

Zone:

Updated At: 31.01.2023, 12:04

Class:


Responsible:



Description: Panel damaged

Corrective Actions: Repair panel

Notes:





#2	#10 FWD BULKHEAD POCKET DOOR	
Category: Interior		Created By [REDACTED]
Sub-Category:		Created At: 31.01.2023, 11:57
Zone:		Updated At: 31.01.2023, 12:04
Class:		Responsible: [REDACTED]
Description: Foam worn		
Corrective Actions: TBD by [REDACTED]		
Notes:		
<div></div> <div></div>		



#3

#20 GALLEY ANNEX

Category: Interior

Created By: [REDACTED]

Sub-Category:

Created At: 31.01.2023, 11:57

Zone:

Updated At: 31.01.2023, 12:04

Class:

Responsible [REDACTED]

Description: Light lens cracked

Corrective Actions: TBD b [REDACTED]

Notes:



#4

#21 FWD RH WALL ASSY

Category: Interior

Created By

Sub-Category:

Created At: 31.01.2023, 11:57

Zone:

Updated At: 31.01.2023, 12:04

Class:

Responsible

Description: Water damage

Corrective Actions: Repair wood

Notes:



#5

#27 FWD DIVAN STORAGE UNIT

Category: Interior

Sub-Category:

Created At: 31.01.2023, 11:57

Zone:

Updated At: 31.01.2023, 12:04

Class:

Responsible

Description: Composite damages caused by improper handling and packing

Corrective Actions: Repair panel

Notes:



#6

#36 RH CABIN TO LAVATORY BULKHEAD

Category: Interior

Created B : [REDACTED]

Sub-Category:

Created At: 31.01.2023, 11:57

Zone:

Updated At: 31.01.2023, 12:04

Class:

Responsible: [REDACTED]


Description: Delamination of wood



Corrective Actions: Wood repair


Notes:



#7	#41 CABIN TO AFT LAVATORY DOOR	
Category: Interior		Created B [REDACTED]
Sub-Category:		Created At: 31.01.2023, 11:57
Zone:		Updated At: 31.01.2023, 12:04
Class:		Responsible: [REDACTED]
Description: Wood damage		
Corrective Actions: Repair wood		
Notes:		
		
		
		
		



#8	#36 RH CABIN TO LAVATORY BULKHEAD	
Category: Interior	Created B : [REDACTED]	
Sub-Category:	Created At: 31.01.2023, 11:57	
Zone:	Updated At: 31.01.2023, 12:04	
Class:	Responsible: [REDACTED]	
Description: Wood Damage		
Corrective Actions: Wood repair		
Notes:		
<div></div>		



#9

#53 FWD LAVATORY SINK

Category: Interior

Created B : [REDACTED]

Sub-Category:

Created At: 31.01.2023, 11:57

Zone:

Updated At: 31.01.2023, 12:04

Class:

Responsible: [REDACTED]

Description: Plating of fwd lavatory sink worn

Corrective Actions: Replate fwd lavatory sink

Notes:



#10

#56 FWD LH WARDROBE

Category: Interior

Created By:

Sub-Category:

Created At: 31.01.2023, 11:57

Zone:

Updated At: 31.01.2023, 12:04


Class:

Responsible:

Description: Wood damage

Corrective Actions: Wood repair

Notes:



#11

#70 AFT LAVATORY TOILET LID

Category: Interior

Created B : [REDACTED]

Sub-Category:

Created At: 31.01.2023, 11:57

Zone:

Updated At: 31.01.2023, 12:04

Class:

Responsibl [REDACTED]

Description: Surface scratched

Corrective Actions: Repaint

Notes:



#12

#72 FWD LAVATORY LIGHT COVER

Category: Interior

Created By: [REDACTED]

Sub-Category:

Created At: 31.01.2023, 11:57

Zone:

Updated At: 31.01.2023, 12:04

Class:

Responsible: [REDACTED]

Description: Paint chipped

Corrective Actions: Repainting

Notes:



#13

#134 FWD TOILET SEAT BASE

Category: Interior

Sub-Category:

Created At: 25.08.2023, 10:42

Zone:

Updated At: 25.08.2023, 11:16

Class:

Responsible:

Description: Composite damaged on 3 screws inserts

Corrective Actions: Repair panel

Notes:



#14

#123 GALLEY HEADLINER

Category: Interior

Created B : [REDACTED]

Sub-Category:

Created At: 25.08.2023, 10:16

Zone:

Updated At: 25.08.2023, 11:15

Class:


Responsible [REDACTED]



Description: Light lenses dull

Corrective Actions: TBD by [REDACTED]

Notes:





#15	#116, #117, #119, #120 VALANCE PANELS	
Category: Interior		Created By: [REDACTED]
Sub-Category:		Created At: 25.08.2023, 09:54
Zone:		Updated At: 25.08.2023, 11:14
Class:		Responsible: [REDACTED]
Description: 8 ea total attachment clip broken		
Corrective Actions: Order 10 ea attachment clips		
Notes:		
<div></div>		



#16

#84 BAGGAGE BAY DOOR COVER

Category: Interior

Created B : [REDACTED]

Sub-Category:

Created At: 22.08.2023, 15:36

Zone:

Updated At: 25.08.2023, 11:13

Class:

Responsible: [REDACTED]

Description: Fabric torn

Corrective Actions: TBD by [REDACTED]

Notes:



#18

#57 FLIGHT DECK ESPACE HATCH SURROUND

Category: Interior

Created By: [REDACTED]

Sub-Category:

Created At: 22.08.2023, 12:13


Zone:

Updated At: 25.08.2023, 11:10

Class:

Responsible: [REDACTED]


Description: Rubber seal needs replacement matching new cockpit headliner colour**Corrective Actions:** Order new rubber seal in correct colour**Notes:**




#19	#23 COCKPIT PANEL
Category: Interior	Created B : [REDACTED]
Sub-Category:	Created At: 21.08.2023, 16:56
Zone:	Updated At: 25.08.2023, 11:03
Class:	Responsible [REDACTED]
Description: 2 screws missing	
Corrective Actions:	
Notes: FYI	







#20	#20 COCKPIT PANEL
Category: Interior	Created By: [REDACTED]
Sub-Category:	Created At: 21.08.2023, 16:56
Zone:	Updated At: 25.08.2023, 11:03
Class:	Responsible: [REDACTED]
Description: 2 screws missing	
Corrective Actions:	
Notes: FYI	
	



#21

#13, #14 PILOT SEAT AND COPILOT SEAT

Category: Interior

Created B : [REDACTED]

Sub-Category:

Created At: 10.08.2023, 19:18

Zone:

Updated At: 25.08.2023, 11:02

Class:


Responsible: [REDACTED]

Description: Repair of broken panel without engineering



Corrective Actions: Repair panel


Notes:





#22	#14 CO PILOT SEAT
Category: Interior	
Sub-Category:	Created At: 27.07.2023, 15:30
Zone:	Updated At: 27.07.2023, 15:30
Class:	Responsible:
Description: Headrest cover cracked	
Corrective Actions: Repair panel	
Notes:	







#23

#5 PILOT SEAT

Category: Interior

Created B : [REDACTED]

Sub-Category:

Created At: 27.07.2023, 15:25

Zone:

Updated At: 27.07.2023, 15:26

Class:


Responsible: [REDACTED]

Description: Leather cover/ soft pad of seatbelt buckle missing



Corrective Actions: Order 2 ea new soft pads


Notes:






#24	#13 PILOT SEAT
Category: Interior	Created By: [REDACTED]
Sub-Category:	Created At: 27.07.2023, 15:23
Zone:	Updated At: 27.07.2023, 15:23
Status:	Responsible [REDACTED]
Description: Headrest cover cracked	
Corrective Actions: Repair panel	
Notes:	











#25	#5 SINGLE SEAT
Category: Interior	Created By: [Redacted]
Sub-Category:	Created At: 27.07.2023, 14:49
Zone:	Updated At: 27.07.2023, 15:26
Class:	Responsible [Redacted]
Description: Plating scratched	
Corrective Actions: Replating	
Notes:	












#26	#15 OBSERVER SEAT	
Category: Interior		Created B : [REDACTED]
Sub-Category:		Created At: 27.07.2023, 15:23
Zone:		Updated At: 27.07.2023, 15:23
Status:		Finish Date: [REDACTED]
Description: Observer seat not part of work scope		
Corrective Actions: Refurb of Observer Seat		
Notes:		
<div></div>		

